

---

Subject: Welding

Posted by [Anonymous](#) on Wed, 15 Jan 2003 13:43:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You will need some .308 stailless steel wire, and a tig torch.

---