

---

Subject: Re: New Computer Research

Posted by [mision08](#) on Fri, 16 Jun 2006 00:25:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Seems to me that manufacturer would make a BIOS update to fix that. In fact, I am sure there probably is one. This is where the Taiwan info may be handy. I caution anyone to never flash the BIOS of any hardware without full understanding of what the flash will change, and how to do it. If you lose power to the PC during a flash the BIOS chip is done. Unless you have an extra chip and the knowledge and skill to install one. Well, this is where the Taiwan info can be handy. All that being said, I use a 3rd party BIOS from Big Tony at OCZ. If the manufacturer will not write a BIOS fix someone will.

google.com.tw

---