Subject: Slow Vid Card...
Posted by General Havoc on Sat, 30 Aug 2003 14:15:59 GMT

Mainly the KT400 board as I don't use the KT333 ones much now. It seems to effect the FX 5600. I had a lod of the KT400 boards that had a faulty BIOS setting so they need upgrades to enable the 8x AGP. It seemed to fix the problems with the FX 5600 after.