Subject: CD-RW Drive read as a CD-ROM Drive
Posted by exnyte on Wed, 15 Oct 2003 17:17:18 GMT
View Forum Message <> Reply to Message

what type of connection is it? it's possible that 98se doesn't support that type of connection, or the drivers for that type of connection may also need to be updated?