

---

Subject: RENGUARD fix it or drop it  
Posted by [suntar](#) on Thu, 23 Sep 2004 13:22:19 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

overheating on a prescott doesnt seem to make much sence.. exp. if there is watercooling on it....

The 64bit loads at 48C, 1.6 loads at 39C, no idea about the 2500, 2.6 loads at 46C

couldnt be overheating.

\*brain stormen\*

I'll run some more test w/ rengaurd and w/out rengaurd.

Thanks for the help though

---