

---

Subject: Re: Computer fell off a cliff

Posted by [danpaul88](#) on Thu, 29 Sep 2011 08:28:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Could be the thermal sensor became dislodged so the fan controller on the video card has no thermal data to help it decide the correct fan speed so it simply runs at full as a fallback measure.

---