
Subject: OT: USB Port

Posted by [cheesesoda](#) on Sat, 27 Mar 2004 16:42:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

I am trying to get my two usb ports that came with my case to work. i found where i need to place everything except for a green plug. it seems like it needs that plug to work because my computer isn't recognizing my hardware.

my tower is a scorpio

(<http://www.tigerdirect.com/applications/SearchTools/item-details.asp?EdpNo=588181&Sku=A451-3001&CatId=342>)

any help would be appreciated.

Subject: OT: USB Port

Posted by [K9Trooper](#) on Sat, 27 Mar 2004 17:35:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

H1 Colour P1

1 Red 1

2 White 2

3 Green 3

4 Black 4

5 Black Shield

H1 Colour P2

6 Red 1

7 White 2

8 Green 3

9 Black 4

10 Black Shield

http://www.starmount.co.uk/s_usbpin.htm

Subject: OT: USB Port

Posted by [cheesesoda](#) on Sat, 27 Mar 2004 17:52:28 GMT

[View Forum Message](#) <> [Reply to Message](#)

i think i have it plugged in correctly, but there is a green plug that just kinda is there. on the plug's cable it says "28AWG Computer Cable" Would that have anything to do with the usb ports? if not, then i have the usb ports plugged in wrong.

Edit: Maybe if I remove that ground from the pin...hmmm....might just work.

Subject: OT: USB Port

Posted by [K9Trooper](#) on Sun, 28 Mar 2004 15:16:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

Can you post an actual picture of your connectin and board?

Subject: OT: USB Port

Posted by [cheesesoda](#) on Sun, 28 Mar 2004 16:44:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

i actually got it to work...but now it's not working again. i was installing the usb 2.0 driver on it and now it doesn't work. i gotta install the normal one again to get it to work. oh well...im gonna have to figure somthin out.

Subject: OT: USB Port

Posted by [Conan4Life](#) on Sun, 28 Mar 2004 22:23:25 GMT

[View Forum Message](#) <> [Reply to Message](#)

ok an IT guys steps up to the plate

its not regcognized proolly cause its usb 2.0 and windows xp does not regcognize it,

you need to install the drivers in the hardwear manager that came with your main board cd or contact your mobo maker to get the drivers (websight)

you may need to install it as administrator in safe mode

but if anthing they should work like usb 1.1
